

Aviamilano Falco F8L Series 2, G-OCDS, 2 March 1996

AAIB Bulletin No: 7/96 Ref: EW/C96/3/4 Category: 1.3

Aircraft Type and Registration: Aviamilano Falco F8L Series 2, G-OCDS

No & Type of Engines: 1 Lycoming O-320-A3A piston engine

Year of Manufacture: 1958

Date & Time (UTC): 2 March 1996 at 1359 hrs

Location: Fair Oaks Airport, Surrey

Type of Flight: Private

Persons on Board: Crew - 1 Passengers - None

Injuries: Crew - None Passengers - N/A

Nature of Damage: Damage to nose landing gear, cowling and propeller

Commander's Licence: Private Pilot's Licence

Commander's Age: 37 years

Commander's Flying Experience: 2,004 hours (of which 26 were on type)

Last 90 days - 1 hour

Last 28 days - 1 hour

Information Source: AAIB Field Investigation

The following statement was provided to AAIB by the owner/pilot of G-OCDS. The statement was both extremely comprehensive and detailed and the decision was made to publish it essentially verbatim:-

Events

I prepared the aircraft for general flying by filling the main fuel tank with 12.5 gallons and left the wing tanks empty. During the warm-up checks I noticed that the undercarriage up red light was not functioning, but the undercarriage down green indicator was fully serviceable. Given that the Falco has visual, mechanically operated indicators on which I mostly rely, I decided that this did not represent a reason to snag and ground the aircraft.

I carried one passenger.

I took off on Runway 06 at Fair Oaks with 8 octas cloud at 1500ft and visibility around 5 to 8 miles. After take off the undercarriage cycled up successfully and all indications were within limits. Due to visibility below VFR minima, I decided to return to the airfield when I reach Guildford and conduct circuits and landings instead. I joined normally for runway 06 and requested a touch and go which was approved. On downwind I selected undercarriage down at 110 kt. The undercarriage did not cycle down. I checked all levers and circuit breakers and found that the undercarriage circuit breaker had tripped. I moved the undercarriage lever to the full up position. I pressed in the circuit breaker and selected undercarriage down.

The aircraft yawed strongly to the right, but the undercarriage cycled down successfully. My initial reaction was that the wheel had lowered asymmetrically. Upon consideration (after landing), I realised that this was impossible and wondered whether my passenger had inadvertently put weight on the rudder pedals, given that he had earlier fouled the control column with his knees.

I cancelled the touch and go, requested a full stop landing and landed softly and successfully. I then taxied back to the apron and informed the tower that I would be going out again, pending a visual undercarriage inspection. I conducted a thorough visual inspection of the undercarriage, the main gear and the nose gear. I could see no indications that there was any failure, no oil leaks, all connections were sound and bolts and lock nuts were in order.

I decided that I would report the incident and seek advice from the aircraft maintainer later, but as I believed that the aircraft was in a serviceable, flyable condition. I decided to continue the circuit and landing exercise solo.

Second Flight

I requested taxi and was instructed to proceed to 06. I completed all power and pre-flight checks and when ready to depart was advised of a runway change and therefore backtracked down 06 and took off on 24, requesting 2 circuits and landings.

After takeoff, at 100 ft I selected undercarriage up. I did not expect to see a red undercarriage up light as it was unserviceable, but I watched the mechanical indicators carefully and front and left indicators cycled normally. However, just before the cycle was complete there was a slight bump/bang from the area of the nose wheel. However the indicator showed the undercarriage up. I proceeded to downwind and dropped the speed to 85 kt before selecting the undercarriage down. The undercarriage appeared to cycle normally whilst I maintained a wary watch on the main undercarriage indicators. The wing indicators on the left showed the undercarriage down, the aircraft was well balanced and I concluded that the right wheel was also down and I awaited the green undercarriage down light as it is triggered by the nose wheel completing its cycle. No green light showed and I noticed that the nose wheel mechanical indicator showed the nose wheel had not cycled at all. I then noticed that the undercarriage circuit breaker had popped out again. I realised that whilst I had main undercarriage down, I could not confirm that it was locked down and I knew that the nose wheel was not down.

I informed the tower that I could not confirm the status of the undercarriage and requested a low level flight past the tower to confirm the status. I flew past at 200 ft and waggled the wings. The tower informed me that the main wheels appeared down and locked but that the nose wheel was only partly extended. I then requested to leave the circuit before declaring an emergency. I intended to attempt to either recycle the undercarriage or crank it down. I flew to an open area, south of Woking, changed to Farnborough radar for radar information at the suggestion of the tower and

then orbited whilst I worked out a strategy for checking the wheels. I firstly opened the manual crank and attempted to crank the wheels further. It was not possible to crank any further. I then selected the circuit breaker to close and selected undercarriage up. The main gear cycled up successfully. I then selected undercarriage down and watched the circuit breaker. The main wheels cycled down successfully and the circuit breaker popped only after the main wheels were down. I concluded therefore that there must be a mechanical failure on the nose wheel or some kind of electrical fault which trips the electric motor when the nose wheel begins to cycle. I flew around for a further 5 minutes, considering what I needed to do in order to land safely. I advised Farnborough that I wished to change to Fair Oaks and had failed to secure the landing gear. I then requested a second flight past the tower to confirm that following the successful rotation of the gear, that the nose wheel position had not changed. The tower confirmed that the nose wheel was still partly down. I requested confirmation of the precise position and was informed that it was one third down. I then requested permission to land.

The tower asked where I wished to land. I confirmed that I wished to land on the tarmac. The tower advised me that the airport manager requested that I landed to the north of centre line and steer the aircraft onto the grass after landing. I acknowledged the request. On downwind I was asked to orbit to the south of the airfield whilst the emergency services arrived. The tower again asked if I preferred to land on the grass or the tarmac. I felt that the airport preferred me to consider grass and I therefore requested the tower to inform me of the condition of the grass. The tower clearly stated that the grass was mostly waterlogged and relayed the airport manager's confirmation that the choice was entirely mine. I again chose to land on tarmac because I feared the consequences of the propeller digging into mud. I continued to orbit and then requested the tower confirm how long it would be before I could land as I was concerned about my fuel status. I was granted permission to land immediately and proceeded to final. I chose to fly a flat approach at 80kt selecting full flap at 400 ft. At 50 ft I closed the throttle, closed the mixture, switched off the fuel pump and battery master but did not have time to switch off the magnetos. I touched down lightly on the main wheels remaining to the north of centre line and held the nose up until the elevators were against the stops. The nose fell down and the propeller struck the ground. I did not notice the RPM at the time and the aircraft tilted onto the ground and once the cowling struck the ground I felt the aircraft braking very quickly under the friction. I felt I was doing little harm to the runway surface and therefore maintained direction on the tarmac until the aircraft came to a rest. I then plucked out the ignition keys, opened the canopy and ran away from the aircraft.

The emergency services were absolutely professional in every respect, preventing a fire but careful not to damage the aircraft further in the process.

I wish to commend Fair Oaks Information, Farnborough Radar, the emergency services and Fair Oaks flight centre for the absolutely professional manner in which they conducted this emergency and helped me to escape unhurt and minimise the damage to my aircraft.

Upon examination, it was found that the nose wheel had turned through almost 90° and had been jamming against the side of the bay into which it retracts. On the Falco, the nose wheel bay is very narrow and contains a guide which centres the nose wheel steering as the leg retracts, assuming it is within the normal steering range. If this does not happen, then the wheel can foul the side of the bay or the rudder controls as it appears had occurred. The oleo leg cylinder forging itself has an integral lug which operates within the torque link attachment brackets to limit nose wheel steering authority (see photograph). The lug had been broken off by an overload failure but, as the photograph shows, this is not immediately obvious unless one is looking specifically in that area.

With the nosewheel now free to castor without restriction, the centring guide had missed its location and failed to centre the steering.

All three landing gears are powered by a single electric motor which drives screw-jacks to raise and lower the legs. Each retraction cycle is concluded by a microswitch on the nose gear which simultaneously cuts power to the motor and illuminates the 'gear UP' red light as it reaches the fully retracted position. Clearly, the nose gear was fouling structure as it was retracted but the motor continued to run and resulted in tripping of the circuit breaker. Eventually the screw-jack drive shaft failed and, with the shaft broken, it was not possible to hand-crank the landing gear down.

The maintainer states that he has seen similar failures of the steering stop lug when aircraft had been manoeuvred on the ground using mechanical tugs, as opposed to manhandling.