

# MW5(K) Sorcerer, G-MYGS, 4 August 1996

**AAIB Bulletin No: 12/1996**

**Ref: EW/C96/8/1 Category: 1.3**

<b>Aircraft Type and Registration:</b>	MW5(K) Sorcerer, G-MYGS
<b>No &amp; Type of Engines:</b>	1 Rotax 447 piston engine
<b>Year of Manufacture:</b>	1994
<b>Date &amp; Time (UTC):</b>	4 August 1996 at 0935 hrs
<b>Location:</b>	Wyke Champflower, Somerset
<b>Type of Flight:</b>	Private
<b>Persons on Board:</b>	Crew - 1 - Passengers - N/A
<b>Injuries:</b>	Crew - 1 fatal - Passengers - N/A
<b>Nature of Damage:</b>	Aircraft destroyed
<b>Commander's Licence:</b>	Private Pilot's Licence
<b>Commander's Age:</b>	44 years
<b>Commander's Flying Experience:</b>	149 hours (of which 19 were on type) Last 90 days - 9 hours Last 28 days - 4 hours
<b>Information Source:</b>	AAIB Field Investigation

## **Pilot's flying experience**

In April 1975, the pilot started flying training at Biggin Hill Airport; he was awarded a PPL, Group 'A', in March 1976. By April 1985, he had recorded a total of 113 hours; no further flying was recorded until October 1994 when he started training on Spectrum microlight aircraft at Wombleton. In May 1995 he was awarded a PPL, Microlight Aeroplanes, and on 30 May 1995, he first flew the Sorcerer G-MYGS. His last flight before the accident flight was 35 minutes on the previous day. He had a total of 35 hours on microlight aircraft.

## **History of flight**

The pilot planned to take off from Sandy at 0730 hrs for a flight to the Cheddar, Somerset area. The weather was fine and the visibility was good. The pilot was seen to refuel the aircraft from a

jerrican; after the accident, the jerrican was found to be half full of commercial 4 star mogas. As the planned destination was about 105 nm from Sandy, there was no reason to assume other than that the had topped up the tank to its maximum capacity of about 30 litres.

An eye witness at the airfield saw the aircraft take off shortly after 0730 hrs. A primary contact from Debden radar was recorded at 0735:51 hrs, about 1.9 nm south west of the airfield, and was maintained until 0758 hrs; the average track was about 238°(M) and the ground speed was about 53 kt. The position, time, track and ground speed imply a high probability that the contact was G-MYGS and that it left the airfield at about 0734 hrs. No further radar contact was identified and it was not reported again until it was seen approaching the village of Wyke Champflower.

When the aircraft was first seen in the vicinity of the village, it was quite low but the engine appeared to the witnesses to be running normally. As the aircraft descended toward a field to the south west of the village, the engine stopped suddenly. The aircraft appeared to be attempting to land in the field but as it turned south east, into wind, the right wing struck a power cable. The aircraft caught fire shortly after impact. An interruption of the power to the line was logged at 0935 hrs.

### **The accident site**

The area in which aircraft crashed comprised a large field of open pasture, bounded on its northern and eastern sides by public roads and transected by a pair of 11 kV high tension electricity supply cables on 6.5 metres high wooden poles running parallel with the eastern edge of the field, approximately 100 metres from the boundary. A set of telephone cables on wooden poles ran down the eastern edge of the field, at the boundary with the road. The north-eastern corner of the field was fenced off into what was effectively a small paddock area, in which several horses grazed.

The right wing of the aircraft had become entangled with the western-most of the pair of high tension cables, at a location approximately 200 metres to the south of the paddock area at the north eastern corner of the field. When the emergency services first arrived at the scene, the remains of the aircraft were still hanging by its right wing, partially suspended from the electricity cable which had become trapped in an aileron pulley bracket at the junction of the main spar and lift strut. The electricity cable was heavily stretched but still intact, and it was evident that during the period immediately following impact, prior to the electrical supply fault detectors finally disconnecting the supply, current had passed through the aircraft structure to earth at those points where the nose and tail of the aircraft contacted the ground. The resulting discharge of current to earth had ignited the tailplane and fuselage pod, and a fierce post impact fire destroyed most of these areas; not only the fabric and plastic parts of the aircraft, but also parts of the aluminium frame. There was no evidence of arcing or fire at the point where the left outer wing contacted the ground, almost certainly because the metal structure was insulated from the ground at this point by the surrounding non-metallic wing skins and tip fairing.

### **Examination of wreckage**

The aircraft was largely destroyed in the post impact fire. However, sufficient remained to allow the pre-crash integrity of the flying controls and the principal structural elements to be confirmed. The engine throttle cables were present and still connected to the carburettor throttle slide, though the bulk of the carburettor itself was destroyed by the post impact fire. There was no damage on the remains of the propeller indicative of engine power at impact. However, it is possible that the propeller did not contact the ground until a relatively late stage in the accident sequence, after the

aircraft had engaged the wires; consequently, the condition of the propeller, alone, cannot be taken as positive evidence that the engine had stopped prior to impact. The fuel tank and fuel supply pipes were destroyed by the post impact fire, which also consumed all other flammable materials in and around the fuselage pod, and it was not possible to determine whether fuel was present in the tank at the time of the accident.

The engine was subsequently examined at AAIB Farnborough. The crankshaft turned freely, and subsequent dismantling of the engine showed it to be in excellent condition mechanically. The appearance of the front spark plug suggested that the front cylinder may have been running slightly richer than the rear; however, both plugs were of normal appearance, and there was no suggestion of an abnormally rich mixture. The engine casing had suffered heating in the post impact fire, resulting in partial melting of ignition system low tension cables at points of contact with it, and both high tension ignition coils were destroyed by the fire. The ignition generator coil was disconnected from the heat damaged cables and its resistance checked and found to be within limits. The ignition timing and contact breaker points were also checked and found set within limits.

Each of the carburettor jets was of the correct type. The throttle barrel was burned away by the fire, but the main jet needle was recovered with the attachment circlip still in place at 'position 3', *ie* one position off the richest setting; a normal setting.

### **Aircraft performance**

The Pilot's Operating Handbook recommends that the aircraft be flown in the cruise at "trim speed" which is factory set at 58 kt and is achieved with a power setting of 5,800 RPM. It also contains a section headed RANGE; this states that the Sorcerer "uses approximately 12 litres of fuel per hour at normal power settings" and quotes the zero wind range as approximately 145 nm. It does not define "normal power settings", however, the range and fuel consumption quoted would imply an rpm of 5,500 and an airspeed of 55 kt. Had the aircraft been flown at the trim speed power setting of 5,800 RPM the fuel consumption would have been about 14.5 litres per hour. The accident site was about 238°(M)/105 nm from Sandy and the flight time was about 2:01 hrs; the aftercast wind at 2,000 feet was 130°/12 to 15 kt.