

# Gemini Flash IIA, G-MVEP

## AAIB Bulletin No: 2/98 Ref: EW/C95/10/5 Category: 1.4

<b>Aircraft Type and Registration:</b>	Gemini Flash IIA, G-MVEP
<b>No &amp; Type of Engines:</b>	1 Rotax 503 piston engine
<b>Year of Manufacture:</b>	1988
<b>Date &amp; Time (UTC):</b>	27 October 1997 at 1059 hrs
<b>Location:</b>	Roydon Hamlet, Essex
<b>Type of Flight:</b>	Private (Training)
<b>Persons on Board:</b>	Crew - 1 - Passengers - None
<b>Injuries:</b>	Crew - 1 fatal - Passengers - N/A
<b>Nature of Damage:</b>	Aircraft destroyed
<b>Commander's Licence:</b>	Student pilot
<b>Commander's Age:</b>	43 years
<b>Commander's Flying Experience:</b>	31 hours (all of which were on type) Last 90 days - 18 hours Last 28 days - 11 hours
<b>Information Source:</b>	AAIB Field Investigation

### History of flight

The pilot was on a qualifying solo cross-country flight for the award of a Private Pilot's Licence. The planned route was from Hunsdon Airfield, near Harlow, Essex to Headcorn Airfield in Kent, where the aircraft would be refuelled for the return flight to Hunsdon. There was low cloud in the area and the pilot was briefed to return to Hunsdon if this became a problem; the planned altitude was 1,500 feet initially and then 2,000 feet.

The pilot had programmed his route into his Global Positioning System (GPS) equipment. Data stored in the GPS was used to determine, in part, the history of the flight. At 1032 hrs, the aircraft took off from Hunsdon Airfield and flew a complete left hand circuit before tracking south down the western side of Harlow. At 1042 hrs the aircraft turned left and tracked east, over Junction 7 of the M11 towards the village of Moreton. At 1051 hrs, shortly before it reached Moreton, it made

a 180° turn to the left and tracked along the southern edge of Harlow. It then turned to track north and, shortly afterwards, the GPS stopped logging data. The last relevant position logged was at 1058 hrs after the aircraft had started a left turn in a position about 260 metres northeast of the accident site. The final part of the track was confirmed by comparing it with recorded data from Heathrow radar; the time of the final return was also 1058 hrs.

Witnesses were consistent in their observations. They reported hearing a sharp 'crack' and seeing the left wing move up almost to the vertical. Shortly afterwards the right wing did the same and, the aircraft spiralled to the ground with the wings folded together and the trike assembly describing a circle beneath them. The aircraft was in the vicinity of the final GPS/radar contact when the observations were made and one witness called the emergency services while it was still falling; the call was recorded at 1058 hrs. The AAIB was unaware of anyone who saw the aircraft in normal flight.

The pilot survived the impact but died shortly afterwards from his injuries. Post mortem examination revealed no pre-existing medical condition which would have contributed to the accident.

### **Pilot's flying experience**

The pilot started a course of microlight flying training in March 1997. Initial training was in a Mainair Blade aircraft. His first flight in the Gemini Flash IIA, G-MVEP, was on 26 August 1997. He made good progress through the course and went solo on 20 September 1997 after 19 hours. His last flight before the accident was on 26 October 1997, after which he had flown a total of 19 hours dual and 1140 hours solo.

### **Meteorology**

An aftercast was obtained from the Meteorological Office at Bracknell. There was a weak cold front lying from Kings Lynn to Folkestone; it was moving slowly westwards.

Surface wind 100°/10 kt

2,000 feet wind 130°/15 kt

Visibility 9 km

Cloud FEW base 600 feet

SCT base 1,000 feet

BKN base 4,500 feet

Temp/Dew point +10C/+8C

QNH 1027 mb

### **Global positioning system**

The GPS equipment carried in the aircraft worked throughout the accident flight. It uses satellite navigation to establish its position which it then displays on a small screen. The equipment has a logging facility which saves position, time and date in non-volatile memory, on a periodic basis when direction or speed change significantly. The equipment was found to operate satisfactorily after the accident.

The data logged during the accident flight was downloaded onto a computer. As the downloaded data was based on a datum other than that used for Ordnance Survey maps, a correction factor was applied to each latitude/longitude point logged and the results plotted onto a 1 to 25,000 map. The plotted points correlated well with the known positions of the take off and the accident. It was not possible to determine the height of the aircraft during any part of the flight as GPS altitude, although displayed on the screen, is not logged in the non-volatile memory.

From 1058 hrs, the GPS stopped logging data for a period of twenty-four minutes. It is considered that this was because the GPS was unable to receive sufficient satellite signals to calculate its position.

It was probably carried in the document pocket on the right side of the aircraft and consequently the accuracy of the recorded data may have been degraded because of satellite obscuration by the pilot or the metal framework of the aircraft. This degradation may have been more noticeable when tracking west as five of the eight satellites in view would have been behind the aircraft.

Further geographical positions consistent with that of the accident site were recorded in the equipment; two points at 1122 hrs, two points at 1229 hrs and a period of uninterrupted operation from 1406 hrs to 1443 hrs. It is likely that, as the aircraft wreckage was moved during the post accident recovery, the GPS may have periodically received adequate satellite signals before it was eventually turned off when the AAIB arrived on the scene.

### **Accident Site**

The microlight was found laying on its left hand side with the wing folded in two. The only significant ground mark had been made by the muffler and did not show any signs of aircraft rotation. The guarded magneto switch was found in the 'off' position. The aircraft was carrying 50 kg of ballast in an appropriate container.

The propeller had disintegrated and the majority of it was retrieved from a 400 metre long trail, however only 45% of the leading edge was recovered. The fabric nose cone was found 275 metres from the accident site along the line of the propeller debris. No vibration damage was apparent on the engine mounts, muffler, air filter or engine casing.

Subsequent examination at the AAIB facility at Farnborough revealed heavy indentations on the lower left hand side of the keel, and wood dust embedded in the left vertical face of the keel fabric in the area over the indentations. The indentations were very similar to keel damage on another wing which was known to have had a propeller strike on the keel.

The following structural damage had occurred before the microlight hit the ground:

The outer 1.33 m of both leading edge tubes had broken in a downwards direction.

The right hand leading edge tube had detached from the nose plate.

The control bar had failed at the inner end of the right handgrip by being forced through the front strut; the front strut had a corresponding slight bend.

The wires on the upper wing did not show any curling typically associated with excessive tension, and the king post was undamaged by compression. The structural damage was consistent with negative 'g' and the trike 'dropping into the wing'. The aircraft had a renewal of its certificate of validity on 30 July 1997 and had flown for a total of 152 hours, and the log book did not contain any record of significant maintenance actions.

The ASI and the altimeter were checked and found to be satisfactory. Detailed examination of the microlight revealed the failure of a muffler spring and an upper side wire ferrule. Whilst these failures had occurred after the loss of control and subsequent structural failure, the details are given below in the interests of flight safety.

### **Muffler Spring Failure**

The hook end on one of the three muffler springs had failed and, although the area on the accident site around the muffler impact mark had been examined closely, the failed end was not recovered. The fracture surfaces were therefore examined to determine whether the failure had been caused by fatigue, and hence the hook could have struck the propeller, or whether the failure had been in overload.

The fracture surface had started from a pre-existing groove in the spring material, and the failure had then propagated to the circumference of the spring. The groove was in a position that could only have been reached by the locking wire used to retain the spring body to the muffler in the event of the spring failing. However, the locking wire fitted showed no similar wear pattern. It was therefore concluded that the wire had been renewed, and that a previous locking wire had worn the groove. The spring had subsequently failed. There was no evidence to support the theory that the spring had failed before the propeller disintegration, however the vibration after the disintegration, or the ground impact could both have produced forces sufficient to overload and break the weakened spring.

The illustrations are shown overleaf.

Insufficient evidence of this accident has been accumulated to determine the cause with any degree of confidence. The AAIB therefore intend to rebuild the sail, using as many of the original parts as possible, with the initial objective of determining the pitch moment and stall characteristics of this specific wing. The results of these tests will be published when they are available.