ACCIDENT

Aircraft Type and Registration: Kolb Twinstar Mk III Xtra, G-CGZA

No & Type of Engines: 1 Jabiru 2200A piston engine

Year of Manufacture: 2013 (Serial no: PFA 205-14316)

Date & Time (UTC): 4 June 2015 at 1130 hrs

Location: Swinefleet Common, Swinefleet, Yorkshire

Type of Flight: Private

Persons on Board: Crew - 1 Passengers - None

Injuries: Crew - None Passengers - N/A

Nature of Damage: Propeller loss and damage to the tailboom

Commander's Licence: National Private Pilot's Licence

Commander's Age: 63 years

Commander's Flying Experience: 288 hours (of which 83 were on type)

Last 90 days - 13 hours Last 28 days - 2 hours

Information Source: Aircraft Accident Report Form submitted by the

pilot

The propeller separated from the engine in flight, without warning and damaged the tail boom. The pilot was able to carry out an emergency landing without incident. The propeller was not recovered, but photographs taken of the fracture faces of the propeller retaining bolt shanks, which had remained attached to the engine crankshaft, showed clear evidence of failure due to the presence of high cycle fatigue. As a result if this incident, and two similar events¹, the Light Aircraft Association (LAA) have confirmed that they are in discussion with the engine manufacturer regarding the issue. Additionally details of the event, together with the recommended procedures for propeller attachment, have been published in the July edition of the LAA's engineering "Safety Spot" (http://www.lightaircraftassociation. co.uk/2015/Magazine/Jul/SafetySpot.pdf).

Footnote

© Crown copyright 2015 65

¹ AAIB Bulletin 09 2007, G-CDFA, Ref EW/G2007/04/20 (https://www.gov.uk/aaib-reports/kolb-twinstar-mk-3-extra-g-cdfa-6-april-2007) and ATSB report A0-2013-046 (https://www.atsb.gov.au/publications/investigation_reports/2013/aair/ao-2013-046.aspx)