



Engineering examination of the fuel cock could find no fault except general drying out and stiffness due to lack of use. The owner stated that it was common practice to leave the fuel cock permanently in the ON position.