## CORRIGENDUM

AAIB Bulletin No 11/90, page 22

Accident to Piper PA28-180, G-BAWX at Sherburn-in-Elmet on 26 August 1990

The threshold speed of the aircraft was incorrectly reported as 80 knots. The actual speed of the aircraft was 80 mph.

ark area where two parametries discribanised and discrovered from a by-stander the exact location of a paramen's house. They set out on foot to are adjusted an aerial search and decided to land about 10 inding site closer to be patient's single-storey chaler house on a grassed area which was peroximantly 20 metres wide and 40 metres long. On approach to the landing site, at a beight the remainder to be 30 ft above ground level, he suddenly expérienced a restriction in tail rotor ontrol. The helicoper commenced a rapid yaw to port which he could not contain and so he lowered as collective lever to reduce the yaw and initiate an emergency fanding. The aircraft rotated to his left and approximately 3% turns before contexting the ground in a wings-level but slightly rail-down and the collective fully and the helicoper stopped rotating after a further 30° of yaw finally coming onest close to the intended direction. The approach and electrics were shouldown and the commander, who was unhurt, vacated the aircraft rough the ramal exist door.