Boeing 737-436, G-DOCH

AAIB Bulletin No: 9/99 Ref: EW/G99/06/38 Category: 1.1

Aircraft Type and

Boeing 737-436, G-DOCH

Registration:

No & Type of Engines: 2 CFM56-3C1 turbofan engines

Year of Manufacture: 1991

Date & Time (UTC): 27 June 1999 at 0940 hrs

Location: Aberdeen Airport

Type of Flight: Public Transport

Persons on Board: Crew - N/K - Passengers - N/K

Injuries: Crew - N/K - Passengers - N/K

Nature of Damage: Serious damage to the starboard horizontal stabiliser tip

Commander's Licence: N/K

Commander's Age: N/K

Commander's Flying

Experience:

N/K

Last 90 days - N/K

Last 28 days - N/K

Information Source: Aircraft Accident Report Form submitted by the aircraft and

airport Operators

The driver of a set of motorised passenger steps, who had been tasked with servicing an inbound Boeing 757 flight on Stand 7, was stationary behind a Boeing 737, G-DOCH, that was parked on Stand 6. After the inbound aircraft arrived on-stand the driver moved the motorised steps forward and collided with the tip of the starboard horizontal stabiliser of the Boeing 737, G-DOCH. The impact, which was also felt on the flight deck, caused a member of the cabin crew of G-DOCH to fall over. Inspection of the scene by the airport management revealed that G-DOCH was parked approximately 1 metre short of the Stand stop mark which resulted in the trailing edge tips of the horizontal stabiliser protruding over the white roadway line at the rear of the Stand.