No: 12/89

Ref: EW/G89/09/12

Category: 1c

Aircraft Type

Piper PA22-160 (converted to tailwheel configuration), G-JEST and Registration:

No & Type of Engines:

One Lycoming O-320-B2A piston engine

Year of Manufacture:

1960

Date and Time (UTC):

29 September 1989 at 1755 hrs

Location:

Staverton airport, Gloucestershire

Type of Flight:

Private (pleasure)

Persons on Board:

Crew - 1

Passengers -1

Injuries:

Crew - None

Passengers - None

Nature of Damage:

Right main landing gear collapsed. Propeller, right wing and elevator

bent

Commander's Licence:

Private Pilot's Licence

Commander's Age:

38 years

Commander's Total

Flying Experience:

360 hours (of which 30 were on type)

Information Source:

Aircraft Accident Report Form submitted by the pilot

The aircraft returned to the circuit pattern for landing on runway 04, where the wind was given as 010°/06 kt. A standard approach was flown, followed by a touchdown and roll along the runway centreline but, as the airspeed decayed to around 35 mph, a swing to the left developed which the pilot was unable to correct. As the aircraft left the runway onto the grass, the swing developed into a ground loop and the right main landing gear leg collapsed. There was no fire and the occupants left the aircraft from the normal exit.