

ACCIDENT

Aircraft Type and Registration:	Mainair Blade, G-MYTU	
No & Type of Engines:	1 Rotax 582-2V piston engine	
Year of Manufacture:	1994 (Serial no: 1011-1094-7-W808)	
Date & Time (UTC):	29 May 2012 at 1315 hrs	
Location:	Private strip near Wolvey, Warwickshire	
Type of Flight:	Training	
Persons on Board:	Crew - 2	Passengers - None
Injuries:	Crew - None	Passengers - N/A
Nature of Damage:	Damage to landing gear, propeller, wing tip and 'A' frame	
Commander's Licence:	Private Pilot's Licence	
Commander's Age:	58 years	
Commander's Flying Experience:	4,011 hours (of which 29 were on type) Last 90 days - 46 hours Last 28 days - 24 hours	
Information Source:	Aircraft Accident Report Form submitted by the pilot	

The microlight was being flown on a training flight to practise visual circuits, with an instructor and student on board. The student occupied the front seat. The 345 m grass runway at the private airstrip was orientated 15/30, with the north-westerly direction in use. The surface wind was light and variable, mainly from the west to north-west, and visibility was good with no significant weather.

It was the fourth takeoff, and the microlight became airborne within half of the runway length. Just after becoming airborne, it drifted to the right and the wing struck adjacent standing crops. This caused the

microlight to yaw rapidly to the right, damaging the right wing tip and landing gear. Only one blade of the propeller was damaged, which the pilot thought indicated that the engine was not producing full power when it struck the ground. Although damage to the microlight was significant, neither occupant (both of whom were wearing safety helmets) was injured.

The instructor thought that the student's right foot had slipped off the throttle at a critical stage of takeoff. He had been unable to correct the situation in the short time before the microlight drifted and struck the crops.