

**No: 9/87**

**Ref: 1c**

**Aircraft type and registration:** Gulfstream AA-5A G-BHWR

**No & Type of engines:** 1 Lycoming 0-320-E2G piston engine

**Year of Manufacture:** 1978

**Date and time (GMT):** 6 July 1987 at 1350 hrs

**Location:** Denham Aerodrome, Buckinghamshire

**Type of flight:** Training

**Persons on board:** Crew — 2                      Passengers — None

**Injuries:** Crew — None                      Passengers — N/A

**Nature of damage:** Damaged beyond economic repair

**Commander's Licence:** Private Pilot's Licence

**Commander's Age:** 23 years

**Commander's Total Flying Experience:** 318 hours (of which 60 were on type)

**Information Source:** Aircraft Accident Report Form submitted by the pilot.

Following a normal approach, with full flap, the student pilot flared the aircraft when slightly too high. The instructor took control and applied full power to go around. The aircraft was seen to adopt a high nose attitude but failed to gain height and, shortly afterwards, it struck the ground to the right of the runway.