



the airfield boundary. The pilot estimated the speed of the aircraft to be about 5 kt as it entered the longer grass. The aircraft immediately ran into a discarded item of farm machinery, which had become overgrown and hidden from the pilot's view. The collision caused damage to the propeller and the left wing. The pilot shut down the aircraft and he and his passenger vacated the aircraft via the normal exits. The airfield emergency services were alerted by a departing aircraft and attended the scene.

The meteorological conditions were recorded shortly after the time of the accident. The visibility was greater than 10 km, there was no significant cloud or weather and the surface temperature was +23°C. The surface wind varied between 150° and 230° with a speed of 10 to 15 kt.