No: 10/87 Ref: 2c

Aircraft type

and registration: Campbell Super Cricket G-AXVK Gyrocopter

No & Type of engines: 1 Volkswagen 1600-2074 piston engine

Year of Manufacture: 1970

Date and time (UTC): 16 July 1987 at 1425 hrs

**Location:** St Merryn Airfield, Cornwall

Type of flight: Private (pleasure)

**Persons on board:** Crew -1 Passengers - None

Injuries: Crew — None Passengers — N/A

Nature of damage: Substantial damage to the rotor, mast and propeller. The engine

and its attachments were also damaged

Commander's Licence: Private Pilot's Licence

Commander's Age: 57 years

Commander's Total

Flying Experience: 151 hours (of which 9 were on gyrocopters)

Information Source: Aircraft Accident Report Form submitted by the pilot.

Whilst making an approach to land, the pilot allowed the speed to fall off to a point where control was lost. At 3—4 feet above the ground, the aircraft drifted and rolled to the left and the rotor made contact with the runway as the aircraft fell onto its left side.

The pilot managed to climb out but there was a small fire caused by fuel spilling onto the hot exhaust manifold. This was quickly extinguished by an instructor using a portable extinguisher.