



APPENDIX 1




First missed approach (ground track)

APPENDIX 2




First missed approach (descent profile)

APPENDIX 3




Second missed approach (ground track)

APPENDIX 4




Second missed approach (descent profile)

APPENDIX 5



Low level visual circuit (ground track)

APPENDIX 6




UTC

19:23:12

19:28:12

19:33:12



Second and third approach (time history)

APPENDIX 7




Figure 1 VOR/DME approach for Runway 26

Reproduced with permission of JEPPESEN & CO. GmbH
 Copyright 1998 JEPPESEN & CO. GmbH

APPENDIX 7




Figure 2 Airfield information

Reproduced with permission of JEPPESEN & CO. GmbH
 Copyright 1998 JEPPESEN & CO. GmbH

APPENDIX 8




Figure 1 View of left main gear

APPENDIX 8




Figure 2 **View of left horizontal stabiliser**

APPENDIX 8



Figure 3 **View of damage to rear fuselage**

