






SECTION OF ENGINE SHOWING LOW PRESSURE STATOR VANE LOCATION



**EXPANDED VIEW OF STATOR LOCATION
(T.G.T. PROBE OMITTED FOR CLARITY)**



**PHOTOGRAPH SHOWING DAMAGE TO
L.P. TURBINE COMPONENTS.**



**PHOTOGRAPH SHOWING CIRCUMFERENTIAL
FRACTURE OF TURBINE CASE**