No: 8/92 Ref: EW/G92/06/10 Category: 1c

Aircraft Type and Registration: Soko P-2 Kraguj, G-BRXK

No & Type of Engines: 1 Lycoming GSO-480-B1A6 piston engine 10 and 1 & old

Year of Manufacture: 1977

Date & Time (UTC): 15 June 1992 at 1135 hrs

Location: Breighton Airfield, North Yorkshire

Type of Flight: Private

Persons on Board: Crew - 1 Passengers - None of the Passengers - None o

Injuries: Crew - None was Passengers - N/A

Nature of Damage: Port landing gear support structure collapsed, damaging

the adjacent skin of the upper and lower wing leading

edge. Propeller tips bent.

Commander's Licence: Private Pilot's Licence with IMC rating

Commander's Age: 34 years of smooth a second season and a second season and a second season and a second season as a second sea

Commander's Flying Experience: 247 hours (one on type)

Last 90 days - 20 hours Last 28 days - 19 hours

**Information Source:** Aircraft Accident Report Form submitted by the pilot

The aircraft was flying from Wombleton, in South Yorkshire, to Breighton and it was the intention of the pilot to investigate its stalling and low speed handling characteristics during the flight. The wind at Breighton was 290°/08 kt and the aircraft made a standard overhead join for a left circuit to land on the 600 metre long grass runway 29. The undershoot area immediately before the runway was 10 metres of paved surface, preceded by a crop of corn standing one to two feet high.

When the aircraft was on short final approach, with the speed reducing from 115 km/hr to 105 km/hr as recommended in the Pilot's Notes, it suddenly sank into the corn crop about 20 metres from the runway threshold. The aircraft immediately ground looped 180° to the left, breaking the port landing gear, and came to rest with the engine stopped.

There was no fire and the pilot's full safety harness withstood the forces of the impact.