AAIB Bulletin No: 8/94 **Ref: EW/G94/05/02** **Category: 3**

Aircraft Type and Registration:	Cameron A180 Hot Air Balloon, G-SKYR	
No & Type of Engines:	N/A	
Year of Manufacture:	1992	
Date & Time (UTC):	1 May 1994 at 1750 hrs	
Location:	Denchworth, Oxfordshire	
Type of Flight:	Public Transport	
Persons on Board:	Crew - 1	Passengers - 9
Injuries:	Crew - None	Passengers - 1 Serious 1 Minor
Nature of Damage:	None to balloon	
Commander's Licence:	Commercial Pilot's Licence	
Commander's Age:	42 years	
Commander's Flying Experience:	480 hours (of which 134 were on type) Last 90 days - 16 hours Last 28 days - 6 hours	
Information Source:	Aircraft Accident Report Form submitted by the pilot	

The pilot made a normal landing in a grass field; the surface wind was 8 kt. On landing, the balloon contacted a surface undulation which caused heavy jarring of the basket and two passengers suffered ankle injuries.