No:2/85 Ref: EW/G84/12/01

Aircraft type and registration: Robin DR400/140 G-BBJU (light single engine fixed wing aircraft)

Year of Manufacture: 1983

Date and time (GMT): 1 December 1984 at 1415 hrs

Location: Dalkeith Farm, Winwick, Huntingdon, Cambs.

Type of flight: Private (Pleasure)

Persons on board: Crew -2 Passengers - None

Injuries: Crew — None Passengers — None

Nature of damage: Substantial — to nose gear leg, propeller, canopy and left land gear leg

Commander's Licence: Private Pilot's Licence

Commander's Age: 45 years

Commander's total flying

experience: 240 hours (of which 34 were on type)

Information Source: Aircraft Accident Report Form submitted by the pilot

The aircraft was taking off on a grass strip aligned east to west and 750 yds long by 30 yds wide. The wind from 180° at $05 \, \mathrm{kt}$, temperature $+ \, 10^{\circ} \mathrm{C}$, with a clear sky. The grass was reported to be wet, and some $4 \, \mathrm{to} \, 5$ ins high. After pre-take off and carburettor heat checks were carried out, the aircraft commenced its take off run with 15° of flap set and an initial engine rpm of 2,300. The aircraft had achieved an IAS of $40 \, \mathrm{kt}$ halfway down the runway but did not accelerate past this figure. The take-off was abandoned and the aircraft overran the grass strip coming to rest inverted in a ploughed area. The upper torso restraints remained intact, and the pilots, who were uninjured, were able to extricate themselves from the aircraft.