

ACCIDENT TO PIPER PA-28R-180, G-BAPW - AAIB BULLETIN 9/89

The CAA are satisfied that the power cables involved in this accident do not penetrate the obstacle limitation surfaces, which include the approach surface associated with the visual runway 27, at Haverfordwest. This surface is clear of all obstructions and therefore meets the licensing criteria for a code 2 visual runway.