

**No: 6/91**

**Ref: EW/G91/03/08**

**Category: 1c**

**Aircraft Type and Registration:** Piper PA-18-150, G-BGWH

**No & Type of Engines:** 1 Lycoming O-320-A2B piston engine

**Year of Manufacture:** 1961

**Date & Time (UTC):** 13 March 1991 at 1720 hrs

**Location:** Clacton Airfield, Essex

**Type of Flight:** Private

**Persons on Board:** Crew - 1                      Passengers - 1

**Injuries:** Crew - None                      Passengers - None

**Nature of Damage:** Damage to main landing gear structure

**Commander's Licence:** Commercial Pilot's Licence with Instructor rating

**Commander's Age:** 56 years

**Commander's Flying Experience:** 2,824 hours (of which 289 were on type)

**Information Source:** Aircraft Accident Report Form submitted by the pilot

During the landing run on runway 36, in a wind of 060°/10 kt, the pilot over corrected a swing to the right, causing a ground-loop which took the aircraft off the left side of the runway.