

No: 4/85

MICROLIGHT

Ref: EW/G84/08/19

Aircraft type and registration:	Gemini Sprint Microlight G-MMSF (single engined microlight aircraft)
Year of Manufacture:	1984
Date and time (GMT):	9 August 1984 at 1030 hrs
Location:	Field at the side of Kirkbride Aerodrome
Type of flight:	Training
Persons on board:	Crew — 1 Passengers — 1
Injuries:	Crew — 1 (serious) Passengers — None
Nature of damage:	Aircraft destroyed
Commander's Licence:	Private Pilot's Licence.
Commander's Age:	46 years
Commander's total flying experience:	1200 hours (of which 600 were on type)
Information Source:	Aircraft Accident Report Form submitted by the pilot.

The instructor was demonstrating a practice forced landing from the downwind position. He misjudged the approach and the aircraft was destroyed on impact with a fence to the left of the runway. The student was unhurt but the instructor suffered a broken wrist, having been save from more serious injury by the fibreglass cockpit moulding.