No: 9/91

Ref: EW/G91/06/32

Category: 1c

Aircraft Type and Registration: Cessna 152 Commuter, G-SACA

No & Type of Engines: 1 Lycoming O-235-L2C piston engine

Year of Manufacture: 1978

Date & Time (UTC): 29 June 1991 at 1220 hrs

Location: Goodwood airfield, West Sussex

Type of Flight: Private

Persons on Board: Crew - 1 Passengers - None

Injuries: Crew - None Passengers - N/A

Nature of Damage: Minor damage to engine mountings, nose landing gear

and steering mechanism

Commander's Licence: Student Pilot

Commander's Age: 57 years

Commander's Flying Experience: 55 hours (of which 52 were on type)

Information Source: Aircraft Accident Report Form submitted by the pilot

The pilot reported that following a steeper than normal approach to runway 24, the flare was initiated slightly high, and this resulted in a heavy landing which caused the aircraft to 'bounce' and pitch forward onto the nosewheel. The aircraft bounced once more and finally came to rest to the right of the grass runway. The pilot, who was wearing diagonal upper torso restraint, vacated the aircraft without injury. The weather at the time was fine with a surface wind of 230°/15 kt.