AAIB Bulletin No: 1/94 Ref: EW/G93/07/40 Category: 1.2

Aircraft Type and Registration: Cessna 421C Golden Eagle, G-NSGI

No & Type of Engines: 2 Continental GTSIO-520-L piston engines

Year of Manufacture: 1980

Date & Time (UTC): 12 July 1993 at about 1530 hrs

Location: Broxton Airfield, Cheshire

Type of Flight: Private

Persons on Board: Crew - 1 Passengers - None

Injuries: Crew - None Passengers - N/A

Nature of Damage: Propeller blades loose and the assembly damaged

beyond repair. Port wing leading edge creased. Port wing upper and lower skins wrinkled and rivets pulled

from rear spar.

Commander's Licence: Private Pilot's Licence with Instrument Rating

Commander's Age: 49 years

Commander's Flying Experience: 3,400 hours (of which 165 were on type)

Last 90 days - 34 hours Last 28 days - 1 hour

Information Source: Aircraft Accident Report Form submitted by the pilot

The pilot states that whilst landing at Broxton, where the grass was wet and long, a normal touchdown resulted in a small amount of pitch-down, causing the left propeller to strike the ground. He was unaware of any damage to the aircraft until it had been parked and put into the hangar. However, the degree of damage caused showed that the ground strike had been very severe, although only on the port side of the aircraft.