No: 11/83

Ref: EW/G83/08/18

Aircraft type and registration:

Avions Robin DR400/140 G-BBCS

(light single engine fixed wing aircraft)

Year of manufacture:

1973

Date and time (GMT):

4 August 1983 at 1553 hrs

Location:

Southend Airport

Type of flight:

Private (Group)

Persons on board:

Crew - 1

Passengers – 2

Injuries:

Crew - none

Passengers - none

Nature of damage:

 $Substantial-damage\ to\ nose\ wheel\ strut,\ propeller,$

and right wing fabric. A VASI was also destroyed

Commander's Licence:

Private Pilot's Licence

Commander's Age

39 years

Commander's total flying

experience:

240 hours (of which 60 were on type)

After a flight from Ostend, the aircraft landed on runway 24 at Southend Airport. The weather was good, with a reported wind of 300°/15 kt and temperature +22°C. After touching down, the aircraft swung to the right and left the paved surface. During this excursion across the grass, the nose wheel assembly struck a VASI and collapsed rearwards. The occupants were uninjured, and evacuated the aircraft safely.