AAIB Bulletin No: 5/93

Ref: EW/G93/01/14

Category: 1c

Aircraft Type and Registration:

Cessna F172M Skyhawk, G-BBJY

No & Type of Engines:

1 Lycoming O-320-E2D piston engine

Year of Manufacture:

1974

Date & Time (UTC):

31 January 1993 at 1630 hrs

Location:

Barton Airfield, Greater Manchester

Type of Flight:

Private

Persons on Board:

Crew - 1

Passengers - None

Injuries:

Crew - None

Passengers - N/A

Nature of Damage:

Aircraft destroyed

Commander's Licence:

Private Pilot's Licence

Commander's Age:

54 years

Commander's Flying Experience: 352 hours (of which 300 were on type)

Information Source:

Aircraft Accident Report Form submitted by the pilot and

telephone enquiries by the AAIB

The pilot was completing a circuit and planning to carry out an overshoot. On finals, as he manoeuvred to the dead side of the northerly grass Runway 09, he became aware of a helicopter hovering nearby. He decided to land and considered that he made a normal landing, although off the runway to the left side. He stated that the nose wheel dug into the soft wet ground and the aircraft overturned.

Observers in ATC commented that the aircraft appeared to flare high and stalled from approximately 20 feet; G-BBJY then overturned immediately after contacting the ground. Weather was good with a wind of 090°/08 kt.