No: 3/91

Ref: EW/G91/01/02

Category: 1c

Aircraft Type

and Registration:

Reims Cessna F172H, G-BMCI

No & Type of Engines:

1 Rolls-Royce Continental O-300-D piston engine

Year of Manufacture:

1969

Date and Time (UTC):

6 January 1991 at 1420 hrs

Location:

Edinburgh Airport, Scotland

Type of Flight:

Private

Persons on Board:

Crew - 1

Passengers - None

Injuries:

Crew - None

Passengers - N/A

Nature of Damage:

Major damage to propeller and wingtip fairing; wing skin rippled

Commander's Licence:

Private Pilot's Licence with IMC and Night ratings

Commander's Age:

32 years

Commander's Total

Flying Experience:

203 hours (of which 130 were on type)

Information Source:

Aircraft Accident Report Form submitted by the pilot

The aircraft had landed on runway 26 with a reported surface wind of 250°/25 gusting 32 kt. Clearance was given to backtrack and a 180° turn was executed. A gust of wind lifted the tail, the nose pitched down and the propeller struck the ground. Shortly afterwards the left wingtip impacted the runway surface and the aircraft pivoted about it, until it was again head into wind. The pilot, who was wearing a diagonal type harness, shut the aircraft down and escaped without injury.

In hindsight, the pilot considered that he may not have applied enough elevator for the wind conditions and that, when the nose started to pitch down, he may have, instinctively, pulled the control column backwards.