

No: 9/88

Ref: EW/G88/07/14

Category: 1c

Aircraft Type and Registration: Gulfstream AA-5A, G-BHKV

No & Type of Engines: 1 Lycoming O-320-E2G piston engine

Year of Manufacture: 1979

Date and Time (UTC): 18 July 1988 at 1815 hrs

Location: Biggin Hill Airport, Kent

Type of Flight: Private (pleasure)

Persons on Board: Crew - 1 Passengers - 1

Injuries: Crew - None Passengers - None

Nature of Damage: Damage limited to noselanding gear and propeller

Commander's Licence: Private Pilot's Licence

Commander's Age: 32 years

Commander's Total Flying Experience: 85 hours (of which 20 were on type)

Information Source: Aircraft Accident Report Form submitted by the pilot

The aircraft was landing on runway 21 in a wind of 250°/12 kts. It bounced on landing and, on the second touchdown, the aircraft swung to the left, left the runway and the noselanding gear collapsed.