No: 6/91

Ref: EW/G91/04/15

Category: 1c

Aircraft Type and Registration:

Fournier RF3, G-BLXH

No & Type of Engines:

1 Rectimo 4AR-1200 piston engine No & Type of Engine

Year of Manufacture:

1964

Date & Time (UTC):

26 April 1991 at 1848 hrs

Location:

Redhill Aerodrome, Surrey

Type of Flight:

Private

Persons on Board:

Crew - 1

Passengers - None

Injuries:

Crew - None

Passengers - N/A

Nature of Damage:

Minor to propeller

Commander's Licence:

Private Pilot's Licence

Commander's Age:

35 years

Commander's Flying Experience: 118 hours (of which 37 were on type)

Information Source: 100 515W 25 1

Aircraft Accident Report Form submitted by the pilot

During a transit flight from Eaglescott, near Barnstaple Devon to Redhill in good weather, the engine of G-BLXH stopped. The pilot transmitted a MAYDAY call which he later cancelled when the engine had been re-started. Some minutes later the engine stopped again but once more it was re-started. The pilot was given ATC clearance through the Gatwick Special Rules Zone direct to Redhill for a straightin approach. Despite a late call of "Gear Check" from the Redhill controller, the aircraft was landed with the landing gear retracted. The same all to same all the besieved and besieved