ACCIDENT

Aircraft Type and Registration: Wolf WII Boredom Fighter, G-BMZX

No & Type of Engines: 1 Continental Motors Corp A65-8F piston engine

Year of Manufacture: 1989

Date & Time (UTC): 8 May 2011 at 1115 hrs

Location: Henham Park, Southwold, Suffolk

Type of Flight: Private

Persons on Board: Crew - 1 Passengers - None

Injuries: Crew - None Passengers - N/A

Nature of Damage: Lower right wing spars broken

Commander's Licence: Private Pilot's Licence

Commander's Age: 44 years

Commander's Flying Experience: 782 hours (of which 198 were on type)

Last 90 days - 11 hours Last 28 days - N/K

Information Source: Aircraft Accident Report Form submitted by the pilot

The pilot stated that, as the aircraft was rolling out after landing at a speed of about 25 mph, he became distracted by a marshaller. As the pilot turned his head back in line with the rollout, he realised that the aircraft was yawed to the left and so he applied full right brake, but was unable to arrest the swing to the left. At the final

point of the ground loop, the right lower wingtip struck the ground, bending it upwards. After the aircraft came to rest, he exited the aircraft normally, having switched off the fuel and electrics. He attributed the accident to "a momentary lapse of concentration".

© Crown copyright 2011 32