No: 9/92 Ref: EW/G92/07/22

Aircraft Type and Registration: Cessna 172F, G-BSOO

No & Type of Engines: 1 Continental O-300-D piston engine

Year of Manufacture: 1964

Date & Time (UTC): 25 July 1992 at 1640 hrs

Location: Langham Airfield, Norfolk

Type of Flight: Private

Persons on Board: Crew - 1 Passengers - None

Injuries: Crew - None Passengers - N/A

Nature of Damage: damage to empennage, left elevator and propeller

Commander's Licence: Private Pilot's Licence

Commander's Age: 68 years

Commander's Flying Experience: 1,984 hours (of which 225 were on type)

Last 90 days - 22 hours Last 28 days - 2 hours Category: 1c

Information Source: Aircraft Accident Report Form submitted by the pilot

The aircraft was using grass runway 02 at Langham airfield; the surface wind was estimated to have been 280°/10 kt. At about 40 mph on the take-off run, the pilot's seat slid back on its rails. The aircraft ran off the runway, to the left, into a field of standing corn. The left main wheel dropped into a furrow which tilted the aircraft to the left as it came to rest. The pilot was uninjured and escaped through the left door.

New seat rails had been fitted in June 1991 and the pilot attributed the accident to his failure to ensure that the seat was positively locked in position.