

**AAIB Bulletin No: 9/93**

**Ref: EW/G93/07/10**

**Category: 1a**

**INCIDENT**

**Aircraft Type and Registration:** BAe ATP, G-BTPJ

**No & Type of Engines:** 2 Pratt & Whitney 126 turboprop engines

**Year of Manufacture:** 1989

**Date & Time (UTC):** 11 July 1993 at 1330 hrs

**Location:** Edinburgh Airport

**Type of Flight:** Public Transport

**Persons on Board:** Crew - 4                      Passengers - None

**Injuries:** Crew - None                      Passengers - N/A

**Nature of Damage:** Damage to left aileron

**Commander's Licence:** Airline Transport Pilot's Licence

**Commander's Age:** 42 years

**Commander's Flying Experience:** 5,027 hours (of which 68 were on type)  
Last 90 days - 68 hours  
Last 28 days - 23 hours

**Information Source:** Aircraft Accident Report Form submitted by the pilot

The aircraft was parked on Stand 9 at Edinburgh Airport; the passengers had not yet boarded. A catering vehicle was manoeuvring on the stand and its rear left corner struck the aircraft's left aileron.