No: 2/88 Ref: 2c

Aircraft type

and registration: Hughes 500D-369D G-HEWS

No & Type of engines: 1 Allison 250-C20B turboshaft engine

Year of Manufacture: 1981

Date and time (UTC): 5 December 1987 at 1500 hrs

**Location:** Ben Aquhallie near Lumphanan, Aberdeenshire

Type of flight: Private (business)

**Persons on board:** Crew -1 Passengers - None

Injuries: Crew — None Passengers — N/A

Nature of damage: Substantial — beyond economic repair

Commander's Licence: Private Pilot's Licence

Commander's Age: 35 years

Commander's Total 220 hours rotary wing (of which approx 100 were on type)

Flying Experience: + 250 hours fixed wing

Information Source: Aircraft Accident Report Form submitted by the pilot and AAIB

telephone enquiry

The pilot was practising autorotative landings and misjudged the flare. The tail rotor struck the ground and the pilot landed immediately, but the aircraft rolled onto its side and was substantially damaged.

The pilot was wearing a full harness, which held on impact and he was uninjured. There was no fire.