No: 10/83

Ref: EW/G83/07/12

Aircraft type and registration: De Havilland DH 89 A Rapide (light twin-

engine fixed wing biplane aircraft) G-AKIF

Year of Manufacture: 1944

Date and time (GMT): 16 July 1983 at 1535 hrs

Location: Sparsholt, near Wantage, Berkshire

Type of flight: Private

Persons on board: Crew -1 Passengers -1

Injuries: Crew – Nil Passengers – Nil

Nature of damage: Substantial to lower left wing. Minor damage

to fairings, fabric, and perspex canopy

Commander's Licence: Private Pilot's Licence

Commander's Age: 37 years

Commander's total flying experience: 1720 hours (of which 12 hours are on type)

The aircraft was landing on a private grass strip, 700 metres in length, and in a direction of 250° magnetic. The wind was estimated at 120°/5–8 kt, and the weather was good. Towards the end of the landing run, the aircraft swung some 45° to the left, and because of the configuration of this aircraft type, the pilot was reluctant to employ heavy braking. The aircraft struck a fence on the left side of the runway, and the lower left wing suffered substantial damage, with minor damage to the fairings, fabric, and perspex canopy.