Category: 1c Ref: EW/G88/08/16 No: 9/88

Aircraft Type

Stampe SV4C, G-AXHC and Registration:

1 Renault 4 PO-3 piston engine No & Type of Engines:

1946 Year of Manufacture:

23 July 1988 at 1800 hrs Date and Time (UTC):

Shipdham Airfield, Norfolk Location:

Private (pleasure) Type of Flight:

Passengers - None Crew - 1 Persons on Board:

Passengers - N/A Crew - None Injuries:

Propeller broken and damage to nose cowling Nature of Damage:

Private Pilot's Licence Commander's Licence

35 years Commander's Age:

Commander's Total 155 hours (of which 17 were on type) Flying Experience:

Aircraft Accident Report Form submitted by the pilot Information Source:

The pilot had refuelled his aircraft and started the engine by hand swinging the propeller before strapping himself into the cockpit. The engine then coughed and stopped and the pilot noticed that the fuel cock was in the closed position. The pilot turned the fuel cock on and checked that the magneto switches were on before leaving the aircraft to swing the propeller once more. The engine started and, due to an increased throttle setting, the tail of the aircraft lifted up. The pilot moved clear but was unable to reach the cockpit in time to prevent the aircraft from nosing over.