No: 6/86 Ref: 1b

Aircraft type Piper PA-28R-200-2 G-BDKV

and registration: No & Type of Engines One Lycoming 10-360-C1C piston engine

Year of Manufacture: 19

1973

Date and time (GMT):

2 May 1986 at 1345 hrs

Location:

Netherthorpe, Yorkshire

Type of flight:

Private (pleasure)

Persons on board:

Crew — 1

Passengers — 2

Injuries:

Crew - None

Passengers — None

Nature of damage:

Minor damage to the right wing

Commander's Licence:

Private Pilot's Licence

Commander's Age:

38 years

Commander's total

flying experience:

197 hours (of which 130 were on type)

Information Source:

Aircraft Accident Report Form submitted by the pilot.

Following an uneventful flight from Bristol, a landing was made on runway 06 at Netherthorpe. The wind was 160°/10 knots and the runway has a down gradient of 1.9%.

The touchdown was made about half way along the 450 metre grass runway and the aircraft overran the end.